## GL: Emergency Relief – SHOPP Emergency Response Program (TIP ID – VAR170008)

Last updated with the 2025 TIP Update

## 2025 FTIP BACK-UP LIST FOR SHOPP - EMERGENCY RESPONSE PROJECTS (VAR170008)

FOR 2022-2028 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PN	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	24/25	25/26	26/27	27/28	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	ALA	580		Near Livermore, at 0.3 mile west of Stonecut	1461D	0P120	201.131	22/23	\$7,149	\$0	\$0	\$0	\$0	\$752	\$1,362	\$105	\$1,270	\$70	\$3,590	\$7,149
				Underpass (PM R4.3L). Restore eroded embankment																
				slope in the eastbound direction and install erosion																
				control measures.																
04	NAP	121	16.0/1	6.1 Near Napa, at Wooden Valley Road. Repair pavement,	2022F	0Q810	201.131	22/23	\$4,422	\$0	\$0	\$0	\$0	\$902	\$1,287	\$173	\$661	\$86	\$1,313	\$4,422
				replace drainage systems, and upgrade guardrail.																
04	SON	121	9.7/1			4K140	201.131	22/23	\$6,219	\$0	\$0	\$0	\$0	\$528	\$941	\$31	\$668	\$11	\$4,040	\$6,219
1 '				Ramal Road. Restore structural integrity of the existing	ı															
				roadway by injecting polyurethane to densify the soil																
				below and minimizing future settlement, grind and																
				replace asphalt concrete, and rehabilitate drainage																
				systems.																
04	ALA	580	1	Near Livermore, at 0.3 mile west of Stonecut	1461M	0P12A	201.131	23/24	\$245	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$245	\$0	\$245
				Underpass. Environmental mitigation project for EA																
				0P120.	00000	0)/000	004.400	00/04	<b>A= 00=</b>	•••	**	•••	•••	**	•••		04.455	•	40.050	<b>A</b> = 00=
04	MRN	37	14.4	,	2922C	0X030	201.130	23/24	\$5,005	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,155	\$0	\$3,850	\$5,005
04	NAD	101	13.4/2	0013. Reconstruct damaged fender system.	2022D	0Q790	201.131	23/24	¢40.404	\$0	\$0	\$0	\$0	¢4 625	\$2,053	\$199	\$1,361	\$639	\$4,304	¢10.101
04	NAP	121	13.4/2	0.7 Near Napa, from 2.8 miles north of Vichy Avenue to 1.4 miles south of Route 128 at various locations. Repair	20220	0Q790	201.131	23/24	\$10,191	<b>\$</b> 0	ΦU	ΦU	φU	\$1,635	\$2,053	\$199	\$1,301	\$638	\$4,304	\$10,191
				and restore slope washouts with Rock Slope Protection	.															
				(RSP), erosion control, steel sheet piles, and drainage	'															
				upgrades.																
04	NAP	29		Near Calistoga, at 2.5 miles south of Lake County line.	2022H	0Q830	201.131	23/24	\$4,986	\$0	\$0	\$0	\$0	\$736	\$1,050	\$118	\$1,200	\$174	\$1,708	\$4,986
	,			Stabilize storm damaged embankment.		04000	2011101	20,2.	ψ.,σσσ	Ψΰ	ų,	Ψ.	40	ψ. σσ	ψ.,σσσ	ψ	ψ., <b>2</b> 00	<b>V</b>	ψ 1,1 00	ψ 1,000
04	SCI	152	20.5/2		2031M	3Q650	201.131	23/24	\$3,409	\$0	\$0	\$0	\$0	\$583	\$492	\$89	\$556	\$168	\$1,521	\$3,409
		1.02	1 20.072	Felipe Road. Stabilize slope with Rock Slope Protection		04000	2011101	20,2.	ψο, ισσ	Ψΰ	Ψ*	Ψ.	40	4000	Ų.02	400	<b>QUOU</b>	ψ.σσ	Ψ1,021	ψο, .σσ
				(RSP), erosion control, and drainage upgrades.																
				, , , , , , , , , , , , , , , , , , , ,																
04	SF	101		In the city of San Francisco, at Cesar Chavez	2922A	0X040	201.130	23/24	\$980	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$230	\$0	\$750	\$980
				Undercrossing Bridge No. 34-0034. Remove and																
				replace damaged bridge deck concrete.																
04	SM	1		Near Pacifica, north of 1st Street. Reconstruct slopes	2921M	4Y080	201.130	23/24	\$1,014	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$234	\$0	\$780	\$1,014
				and replace drainage system.																
04	SM	1		In Half Moon Bay, at 0.2 mile north of Coronado Street.	2922L	0X080	201.130	23/24	\$2,600	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$600	\$0	\$2,000	\$2,600
				Reconstruct slope and repair pedestrian access.																
			L																	
04	SM	35	1.6/3	, , , , , , , , , , , , , , , , , , , ,	2921V	0X000	201.130	23/24	\$2,740	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$632	\$0	\$2,108	\$2,740
				County line to 0.7 mile north of Alpine Road.																
				Reconstruct slopes and unlined ditches, replace culver																
04	SM	101	-	systems, and repair pavement.  In Belmont, at Belmont Creek Bridge No. 35-0018.	2922G	0X060	201.130	23/24	\$3,212	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$741	\$0	\$2,471	\$3,212
04	JIVI	101		Remove debris and sediment from box culvert.	23220	0,000	201.130	23/24	φ5,212	Ψ	Ψ	φυ	φυ	φυ	φυ	Ψ	φ141	φυ	φ2,411	φ5,212
04	SM	8/1	20.6/2		2921T	0X020	201.130	23/24	\$1,236	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$285	\$0	\$951	\$1,236
U4	CIVI	04	20.0/2	0.1 mile north of Haciendas Drive. Repair roadway slip	29211	07020	201.100	20/24	Ψ1,230	Ψ	Ψ	Ψ	φυ	φυ	Ψυ	Ψ	ΨΖΟΟ	ΨΟ	ψουι	Ψ1,230
				out, culvert system, and sink hole.																
04	SON	116	1	Near Jenner, at 1.1 miles east of Route 1. Permanent	20315	0AA63	201.131	23/24	\$6,029	\$0	\$0	\$0	\$0	\$1,130	\$710	\$70	\$710	\$656	\$2,753	\$6,029
Ŭ.	20.1			restoration of slope by reconstructing culvert wingwalls	-0070	27 2 100			70,020	ΨŰ	Ψ.	Ų.	Ψ.	\$ ., . 50	ψ σ	ψ. σ	ψ	<b>4000</b>	\$2,.00	70,020
				and placing Rock Slope Protection (RSP).																
04	SON	1	26.7/2		2911P	0J301	201.131	23/24	\$6,982	\$0	\$0	\$0	\$0	\$0	\$1,000	\$10	\$2,800	\$0	\$3,172	\$6,982
		1	1	Road. Mitigation project for EA 0J300 for plant																
				establishment and erosion control.																
04	SON	101	2.9	Near Petaluma, at 0.4 mile north of Kastania Road.	2923D	3Y910	201.130	23/24	\$2,880	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$650	\$0	\$2,230	\$2,880
		1		Stabilize slope and install rock slope protection and																
				drainage system.																
							ime Extensi			\$0	\$0	\$0	\$0	\$6,266	\$8,895	\$795	\$13,753	\$2,049	\$37,541	\$69,299
04	MRN	101	16.1/1	6.2 Near San Rafael, at 0.5 mile north of Miller Creek	2032N	2AA40	201.131	24/25	\$918	\$926	\$0	\$0	\$0	\$400	\$500	\$18	\$400	\$0	\$526	\$1,844
				Road. Repair slipouts by cutting back slopes and																
		<u> </u>	<u> </u>	placing erosion control.	<u> </u>			<u> </u>												

March 21, 2024 1 of 2

## 2025 FTIP BACK-UP LIST FOR SHOPP - EMERGENCY RESPONSE PROJECTS (VAR170008)

FOR 2022-2028 PROGRAM YEARS
All amounts in \$1,000

Dist	Co	Rte	!	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	24/25	25/26	26/27	27/28	PAED	PSE	<b>RW SUP</b>	CONSUP	RW	CON	TOTAL
04	SM		36		Boulevard. Plant establishment mitigation for project EA 1123U.	2917N			24/25	\$852	\$11,276	\$0	\$0	\$0	\$320	\$532	\$0	\$0	\$11,276	\$0	\$12,128
	MRN				Repair and extend retaining wall, replace culvert and guardrail, and repair pavement.	2906H		201.131	25/26	\$2,988	\$0	\$6,385	\$0	\$0	, , , , ,	\$1,729	\$205	\$1,520	\$39	\$4,826	\$9,373
04	MRN	101	6		In Corte Madera, from 0.4 mile to 0.6 mile north of Route 131 (Tiburon Boulevard). Restore slope, regrade unlined ditch, and install erosion control measures.	2032M	2AA30	201.131	25/26	\$993	\$0	\$3,541	\$0	\$0	\$714	\$964	\$29	\$793	\$36	\$2,712	\$5,248
04	MRN	131	1		In Tiburon, east of Trestle Glen Boulevard. Stabilize roadway by constructing a retaining wall.	2906J	3AA90	201.131	25/26	\$2,421	\$0	\$3,504	\$0	\$0	\$962	\$1,227	\$232	\$630	\$298	\$2,576	\$5,925
,					In the city of Napa, at Sousa Lane; also at 1.4 miles north of Vichy Avenue (PM 12.1). Place new culvert at Sousa Lane, and reconstruct shoulder and place rock slope protection at the second location.	2022E	0Q800	201.131	25/26	\$730	\$1,120	\$1,919	\$0	\$0	\$730	\$940	\$180	\$860	\$62	\$997	\$3,769
04	NAP	128	3		Near Saint Helena, at 1.2 miles east of Chiles Pope Valley Road. Construct retaining wall, rehabilitate drainage system, and install erosion control to stabilize slope.	2906G	4AA30	201.131	25/26	\$1,539	\$1,904	\$7,168	\$0	\$0	\$1,539	\$1,829	\$75	\$1,813	\$44	\$5,311	\$10,611
	NAP				Near Calistoga, at 3.1 miles north of Tubbs Lane. Install wire mesh drapery system.		2W370	201.131	25/26	\$731	\$1,172	\$3,184	\$0	\$0	\$731	\$1,010	\$162	\$1,331	\$64	\$1,789	\$5,087
04	NAP	29	11		In Napa, from First Street to 0.1 mile south of Redwood Road/Trancas Street. Environmental mitigation planting for project EA 0Q820.	2923W	0Q82A	201.131	25/26	\$0	\$313	\$499	\$0	\$0	\$0	\$310	\$3	\$246	\$0	\$253	\$812
04	SON	116	5		Near Guerneville, at 0.2 mile west of Redwood Drive. Repair storm damaged slope by installing soil nail wall.	2909N	0AC30	201.131	25/26	\$753	\$1,111	\$2,986	\$0	\$0	\$753	\$1,026	\$85	\$933	\$137	\$1,916	\$4,850
04	MRN	1			Near Marshall, at 1.2 miles south of Marshall Petaluma Road. Place rock slope protection, replace fence, and repair pavement.	2913H	0W710	201.131	26/27	\$1,400	\$0	\$1,228	\$1,686	\$0	\$1,400	\$1,200	\$28	\$630	\$32	\$1,024	\$4,314
04	SM	1	13		Creek Road to Pescadero Creek Road. Realign roadway inland to address sea level rise and eroding bluff.	2916Q		201.131	27/28	\$1,980	\$0	\$2,080	\$19,677	\$0	\$1,980	\$1,720	\$360	\$3,360	\$488	\$15,829	\$23,737
								ncy Respons						\$0	\$10,583	. ,	. ,	\$12,516		-	\$87,698
					SHOPP - Emergency Response NEW REQUESTED TOTA								\$21,363	\$0	\$16,849	\$21,882	\$2,172	\$26,269	\$14,525	\$75,300	\$156,997

March 21, 2024 2 of 2